

VALUE AND RELIABILITY

MERITOR RED MANUAL SLACK ADJUSTERS



Meritor

**FOR
A WORLD
THAT'S
ALWAYS ON™**





VALUE AND RELIABILITY

For over 100 years Cummins-Meritor has been a leader in axle and braking systems for heavy vehicles. Meritor Red is an extended range of aftermarket braking components brought to you by one of the industry's most trusted names. Our Meritor Red Manual Slack Adjusters are the latest addition to the line-up that delivers confidence and reliability you can count on.

FEATURES AND BENEFITS

FEATURES	BENEFITS
<ul style="list-style-type: none"> Large 19mm adjusting nut is standard across the range 	<ul style="list-style-type: none"> Easier adjustment in adverse and dusty environments and where material build up on the adjuster mechanism is a problem. Only one spanner required to adjust in mixed fleet applications.
<ul style="list-style-type: none"> Heavy duty worm gear material 	<ul style="list-style-type: none"> Durability and longevity of the adjusting mechanism in real world applications.
<ul style="list-style-type: none"> Maximum torque rating 22,000 inch-pounds Approved to Meritor Standards 	<ul style="list-style-type: none"> Proven performance and long life.
<ul style="list-style-type: none"> Large 1/8" bsp lube fitting 	<ul style="list-style-type: none"> Suit auto grease system tubes

SPECIFICATIONS

PART NO.	ARM LENGTH CAM CENTRE TO CLEVIS PIN HOLE(S)	STRAIGHT /OFFSET	SPLINE DIA. & NO. OF TEETH	CLEVIS PIN DIA.	APPLICATION	CROSS REFERENCE	
						ATAP	WATTS
MMSA5020 	Hole 1 (5") Hole 2 (6") Hole 3 (7")	Straight	1-1/2"-10	1/2"	General Purpose Truck & Trailer	BP5020-1	WT5020HD
MMSA5023 	Hole 1 (5-1/2") Hole 2 (6-1/2")	Straight	1-1/2"-10	1/2"	Drive axles	BP5023-1	WT5023HD
MMSA5024 	Hole 1 (5-1/2") Hole 2 (6-1/2")	Straight	1-1/2"-28	1/2"	Drive axles	N/A	WT5024HD
MMSA5025 	Hole 1 (5") Hole 2 (6") Hole 3 (7")	Straight	1-1/2"-28	1/2"	Drive axles	BP5025-1	WT5025HD

MMSA = Meritor Manual Slack Adjuster



Meritor Heavy Vehicle Systems Australia
50 Calarco Drive
Derrimut, VIC 3026
AUSTRALIA

(03) 8353 6050

meritorpartsexpress.com

CMFL083-SLACK ADJUSTERS 01/24
Produced in AUS 01/24
©2024 Cummins Inc.