

In this Issue: Product In Focus • New Products • Supersessions • Special Notice • Staff Profile

PRODUCT IN FOCUS - Euclid King Pin Kits



Features & Benefits

- Low friction bushings (Ezi Steer) help to reduce steering effort and provides longer life.
- Draw keys are threaded for easier service.
- King pin seal prevents lubricant seepage, seals out contaminants and provides improved lubrication system.

King Pin Kits Quick Reference Guide

PART NUMBER	SUITS AXLE	BUSHING	NOTES
E-4442B	FA211 / FA215 / FF901 / FA216	Bronze	
E-4468B	FF931 / FF932	Bronze	
E-4694C	FF941 / FF931 / FF942	Ezi-Steer	
E-4695C	FG941	Ezi-Steer	
E-8373AU*	FG941 / MFS13 / MFS14	Ezi-Steer	Same as E-4695C but with longer keys
E-6868B	FG941 / MFS13 / MFS14	Bronze	
E-4458C	FL931 / FL941 / MFS18 / MFS20	Ezi-Steer	
E-11813C	MFS73 / MFS16	Ezi-Steer	
E-8464AU	MFS73 / MFS16	Bronze	
E-6199C*	FF941 / FF931 / FF942	Ezi-Steer	Same as E-4694C but with longer keys
E-4459B	FORD (WESTPORT) FRONT AXLE	Bronze	
E-11394B	E1000I / E1200I / E1320I	Bronze	
E-TYTK653	E1460I / E1460W	Bronze	
E-TYTK717	E14621 / E1462W	Bronze	
E-4696B	EFA-12FA / EF-13F5	Bronze	



BULLS EYE 2018

BPW AIR SPRINGS CROSS REFERENCE

Meritor carries a range of BPW Air Springs to suit most trailer applications

TRAILER APPLICATIONS						
BPW	Rear Part Number	Rear OE Part Number	Continental Part Number	Firestone Part Number	Goodyear Part Number	Diagram
Туре 30	<u> </u>					
(Service Assembly - Including TOP Plate Only)	MLF8047	05.429.40.03.0 05.429.42.25.0	941 MB / BPW 30	W01 M58 8620	1R11-700	
Complete Assembly (Steel Piston)	MLF8046	05.429.40.28.1 05.429.41.24.1	941 MB / BPW 30	W01 M58 8619	1R11-701	1000 − 00000 − 00000 − 00000 − 00000 − 00000 − 00000 − 00000 − 00000 − 00000 − 00000 − 00000 − 00000 − 000000
Complete Assembly (Plastic Piston)	MLF8093	05.429.43.20.0	941 MB	W01 M58 8619	1R11-743	0203 0000 100 100 100 100
Туре 30К	Туре ЗОК					
(Service Assembly - Including TOP Plate Only)	MLF8045	05.429.40.91.0 05.429.42.20.0 05.429.42.56.0	940 MB	W01 M58 8613	1R11-703	0299 0134 150 - 150 -
Complete Assembly (Steel Piston)	MLF8042	05.429.42.41.1 05.429.40.09.1	940 MB	W01 M58 8609	1R11-763	
Complete Assembly (Plastic Piston)	MLF8177	05.429.43.21.0	940 MB	W01 M58 8613	1R11-703	- 259 - 920
Туре 36						
(Service Assembly - Including TOP Plate Only)	MLF8066	05.429.40.01.0 05.429.40.03.6 05.429.42.26.0	881 B BPW 36	W01 M58 8978	1R14-708	0500 20 20 20 20 050 050 050 050
Complete Assembly	MLF8104	05.429.43.51.0 05.429.43.60.0	881 MB	W01 M58 8667	1R14-748	0311 0332 035 0 0 0 0 0 0 0 0 0 0 0 0 0

BPW Air Springs - CLICK HERE

NEW PRODUCTS & SUPERSESSIONS

NEW PRODUCTS

Part Number	Description
E-4611	TIE ROD END RH

SUPERSESSIONS

Old Part Number	Description	New Part Number
A13235W2779	IAD ASSY RP2014X	A13235V3012
21219322	CAMSHAFT LH 350 610mm	S21219322
21219342	CAMSHAFT	S21219342
21225020	CAMSHAFT	S21225020
21225021	S21225021	S21225021
21227078	CAMSHAFT RH 10S 610mm	S21227078
21227079	CAMSHAFT LH 10S 610mm	S21227079
21227106	CAMSHAFT	S21227106
20RYSM40-24	YOKE MALE, SPLINE	20RYSM40-47
63173	SHOCK ABSORBER	M63173
85703	SHOCK ABSORBER	M85703
R806004	SLACK ADJUSTER AUTO	R806004A
1245R1032	CLEVIS M16X1.5	1245Q1083
948599	SHIM	42X1568
941291	SHIM	42X1567
941292	SHIM	42X1569
941293	SHIM	42X1570

All parts displayed in New Products & Supersessions will be available for immediate ordering. Lead times apply for the listed items. Not all parts are available to Independent Customers. Please contact Meritor Customer Service on (03) 8353 6050 for further information.

For full list of supersessions, CLICK HERE






Special Notice - Meritor Australia Brand Update

Dear Meritor Customer,

Meritor Australia would like to inform you of pending brand changes driven by our recently announced global aftermarket brand: MACH. The launch of an exciting new brand presents a unique opportunity to realign our existing portfolio to better leverage the strength of the Meritor brand. Over the coming months you will notice changes to the packaging and branding of Meritor products. The below graphic illustrates the branding changes we will be implementing at Meritor Australia, beginning from March 2018.



MACH is a completely new brand targeted at the value segment of the market. Meritor Australia plan to introduce the Mach brand to customers in mid-2018. At this stage we have not finalised the suite of MACH products available in Australia, but will keep you informed as we near this date. You can find more information on this brand here: http://www.machtruckparts.com/

The key points to note are:

- Parts which are currently fitted in production will transition from Meritor to Meritor Genuine branding, signifying the OEM quality of the product. These will continue to be available only to Original Equipment Manufacturer (OEM) customers
- The Meritor AllFit brand will be replaced by the Meritor brand (in either Red or Black)
- The Euclid brand will remain however Euclid Brake Shoe Kits will transition to Meritor (Black) brand.
- New Mach product will be introduced mid-way through calendar year 2018
- Meritor will continue to offer a range of Meritor co-branded private label brake shoe kits

We hope these changes will enable you to better utilise our offering to compete in the commercial vehicle aftermarket and ask for your patience and understanding as we transition parts to the new branding over the coming months.

I would also like to take this opportunity to reassure all customers that the described changes are of a packaging and branding nature only and will have no impact upon the quality and reliability of our existing parts.

If you have any questions or concerns regarding the changes please don't hesitate to contact your local Meritor Driveforce[™] Field Representative.

Kind Regards,

Adam Carroll Product & Marketing Team Leader Meritor Australia



BULLS EYE 2018

EMPLOYEE PROFILE - MICHAEL SNELL Role at Meritor: Sales Manager / Year Joined: 1999



What is your background in Sales Management?

I started with Meritor in 1999 in Operations with roles in Quality and Continuous Improvement. In 2003 I moved into the Field Operations Group as a Field Sales & Service Engineer responsible for WA, SA, NT, TAS and a large part of VIC. I then left Meritor in 2006 and moved to the UK. In 2008 I returned to Meritor as the Sales & Marketing Manager for the Truck business unit. In 2013 my role was expanded to include the sales function of the Aftermarket business unit and in 2016 expanded further to include the Marketing function.

What challenges are involved in the role?

The main challenge I have is to ensure that the business keeps growing year-on-year whilst ensuring we meet our customers expectations. Meritor is transitioning to a growth oriented company via the company's M2019 strategy that has been rolled out globally. In order to do this, I need to ensure that the Sales & Marketing team have all the business tools they need to help drive growth.

What interests do you have outside work?

I have a young family so majority of my time outside of work is spent with the family. When I get a chance, I enjoy catching up with my mates for a quiet beer.

