

Product Information Letter

Meritor Heavy Vehicle Systems
Australia Ltd.
A.B.N. 86 004 479 430
70 Berkshire Road (P.O. Box 25)
Sunshine, Victoria, 3020
Tel: (61 3)9311-6555
Fax: (61 3)9312-1810
Aftermarket Service Parts
Tel: (61 3)9312-4322
Fax: (61 3)9310-2911



PRODUCT INFORMATION LETTER # 04-002

Date: April 2004
Subject: Change in Lining Material for DX Disc Brake
Models: DX195 and DX225-21

Dear Customer

Please be advised of a change in brake pad lining material for the DX195 and DX225-21 disc brake assemblies, as fitted on RT145 and RT160 axle product. The new pads are fully interchangeable with the existing pads, however;

Brake pads of differing lining materials must not be used on the same axle group

e.g. on a tandem axle set, R702 brake pads on the forward rear axle must not be used with MA705 brake pads on the rear rear axle. All brake pads must be changed to the same material.

The introduction of the new lining material will be implemented as a running change, starting May 2004, and top level axle numbers will not change.

	<u>Current Part Number</u> (Material Code: R702)	<u>Replacement Part Number</u> (Material Code: MA705)
DX195	A1-3222-T-2308	A7-3222-T-2308
DX225-21	A1-3222-A-2367	A7-3222-A-2367

The use of non genuine parts contravenes ADR compliance.

If you have any questions, please contact an ArvinMeritor representative

Issued by Product Engineering
Meritor HVS Australia

Use only genuine Meritor parts
An ArvinMeritor brand