

# Product Information Letter

**Meritor Heavy Vehicle Systems  
Australia Ltd.**  
A.B.N. 86 004 479 430  
70 Berkshire Road (P.O. Box 25)  
Sunshine, Victoria, 3020  
Tel: (61 3)9311-6555  
Fax: (61 3)9312-1810  
Aftermarket Service Parts  
Tel: (61 3)9312-4322  
Fax: (61 3)9310-2911

The logo for ArvinMeritor, featuring the word "Arvin" in a stylized red font with horizontal lines through it, followed by "Meritor" in a bold red font with a small trademark symbol.

## PRODUCT INFORMATION LETTER # 04-003

**Date:** October 2003  
**Subject:** Central Tyre Inflation Systems  
**Models:** FG941, MFS73 and FL941 Steer Axles

Dear Customer

To ensure product durability in arduous applications using Central Tyre Inflation (CTI) systems, and to accommodate any possible future legislation for increases in GAWR limits for steer axles, ArvinMeritor will no longer offer machined knuckles to suit CTI as an original equipment option on the FG941 axle model.

Either the MFS73 or FL941 are considered to be more appropriate axle models for applications where CTI is likely to be utilised.

As such, machined knuckles to suit CTI will be made available as original equipment on both the MFS73 and FL941 axle models from October 2003.

If you have any questions, please contact an ArvinMeritor representative

Issued by Product Engineering  
Meritor HVS Australia

**Use only genuine Meritor parts**  
*An ArvinMeritor brand*