

Product Information Letter

Meritor Heavy Vehicle Systems
Australia Ltd.
A.B.N. 86 004 479 430
70 Berkshire Road (P.O. Box 25)
Sunshine, Victoria, 3020
Tel: (61 3)9311-6555
Fax: (61 3)9312-1810
Aftermarket Service Parts
Tel: (61 3)9312-4322
Fax: (61 3)9310-2911



PRODUCT INFORMATION LETTER #06-001

Date: April 2006

Subject: Permalube™ Driveline Bolt Replacement During Service.

Models: All Permalube™ (RPL) Drivelines

Dear Customer

ArvinMeritor is pleased to announce that the **Meritor® Permalube™ Driveline (RPL)** is now being specified and supported by production in Australia. As this driveline is now coming into Service it is necessary to advise you that in the event of the driveline being removed for service purposes to mating parts, it is essential that **only new bolts of the correct grade are used** when reattaching the driveline to the Yokes.

Damaged and reused parts can affect driveline operation, which can cause the driveline to separate from the vehicle.

To maintain product integrity it is essential that only Genuine Meritor Replacement bolts are used in replacement.

Table 1 – RPL Driveline Bolt Details:

Driveline Size	Part Number for Bolts	Number Required Per Yoke
RPL 25 – Main Shaft	CSC8-20-52	4
RPL 20 - Inter axle Shaft	CSC8-20-52	4

If you have any questions, please contact an ArvinMeritor representative

Issued by Product Engineering
Meritor HVS Australia

Use only genuine Meritor parts

An ArvinMeritor brand