

Product Information Letter

**Meritor Heavy Vehicle Systems
Australia Ltd.**
A.B.N. 86 004 479 430
70 Berkshire Road (P.O. Box 25)
Sunshine, Victoria, 3020
Tel: (61 3)9311-6555
Fax: (61 3)9312-1810
Aftermarket Service Parts
Tel: (61 3)9312-4322
Fax: (61 3)9310-2911

The logo for ArvinMeritor, featuring the word "Arvin" in a stylized red font with horizontal lines through it, followed by "Meritor" in a bold red font with a small trademark symbol.

PRODUCT INFORMATION LETTER # 06-005

Date: August 2006
Subject: Flitch Plate Discontinuation
Models: RT50-160GP with AC6T

Dear Customer

This Product Information Letter is being issued to advise that application approval for the combination of RT50-160GP fitted with the AC6T suspension is being discontinued.

Warranty will continue to be applied to existing applications, however, any vehicle defined after 1st September 2006 will not be covered.

Suspension brackets for the AC6T will remain as a serviceable item through the normal Aftermarket channels, however, the flitch plate part numbers 3280-L-584A and 3280-M-585A will be no longer be available.

If you have any questions, please contact an ArvinMeritor representative

Issued by Product Engineering
Meritor HVS Australia

Use only genuine Meritor parts
An ArvinMeritor brand