PRODUCT INFORMATION LETTER # 13-004



Meritor HVS Australia Ltd. 70-76 Berkshire Road Sunshine North, Victoria Australia

Date: November 2013

Subject: Change of Carrier Mounting Studs

Models: RT140/145, RT160, RT180 and RT380 Axles

Dear Customer,


Meritor Australia is introducing new carrier mounting studs featuring a pre-applied thread sealant as part of a continuous improvement initiative. The Bill of Material will reflect the new stud part numbers but top-level specifications remain the same and service procedures do not change. This change is effective immediately. The old and new part numbers are listed below;

Old Part No.	New Part No.
4X1531	4X1928
SN1021.1	4X1929
SN1034.1	4X1925
SN1038.1	4X1927
SN1036.1	4X1926

Fitting Studs To Axle Housing – New reference charts

For RT140/145 Series			
Fastener	Туре	Part No.	L (mm)
Α	stud	4X1928	89
В	stud	4X1929	70
Х	cap screw	10X1594	44

145 Series




PRODUCT INFORMATION LETTER # 13-004




Meritor HVS Australia Ltd. 70-76 Berkshire Road Sunshine North, Victoria Australia

For RT160 Series			
Fastener	Туре	New Part No.	L (mm)
В	stud	4X1929	70
С	stud	4X1922	76
D	stud	4X1925	108
E	stud	4X1927	121
L	stud	4X1926	114
Х	cap screw	10X1594	44

For RT180 Series			
Fastener	Туре	Part No.	L (mm)
Α	stud	4X1928	89
В	stud	4X1929	70
D	stud	4X1925	108
Х	cap screw	10X1595	51






PRODUCT INFORMATION LETTER # 13-004



Meritor HVS Australia Ltd. 70-76 Berkshire Road Sunshine North, Victoria Australia



For RT380 Series			
Fastener	Туре	Part No.	L (mm)
Α	stud	4X1928	89
В	stud	4X1929	70
D	stud	4X1925	108

If you have any questions, please contact a Meritor Australia representative on +613 9300 5200.

Issued by Product Engineering

Meritor HVS Australia