

**Date:** April 2017  
**Subject:** Interaxle Driveline Consolidation  
**Models:** RPL & MXL

**Dear Customer,**

As part of a continuous improvement process, Meritor has consolidated and optimised its interaxle driveline product offering. Increasing the amount of slip capability on several assemblies resulted in the consolidation of current production and elimination of unique assemblies with minimal or no sales volume.

The new assemblies are completely interchangeable with those they are replacing and replacement part numbers will be introduced into production when stocks of the current part numbers run out. The tables below provide a listing of all affected interaxle drivelines and a cross reference of current to replacement part numbers.

RPL20	
Current Meritor Number	Replacement Meritor Number
20RHM022C150H	Withdrawn - no replacement
20RHM023C152H	Withdrawn - no replacement
20RHM025C156H	20RHM080C156H
20RHM026C159H	20RHM080C156H
20RHM008C162H	20RHM081C162H
20RHM009C165H	20RHM082C165H
20RHM010C167H	20RHM082C165H
20RHM011C170H	20RHM083C170H
20RHM012C172H	20RHM083C170H
20RHM013C175H	20RHM084C175H
20RHM014C177H	20RHM084C175H
20RHM015C180H	20RHM085C180H
20RHM016C182H	20RHM085C180H
20RHM017C185H	Withdrawn - no replacement
20RHM018C187H	Withdrawn - no replacement
20RHM019C190H	20RHM087C190H
20RHM020C192H	20RHM087C190H

Table 1 - RPL20 Driveline



Meritor HVS Australia Ltd  
70-76 Berkshire Road  
Sunshine North, Vic Australia

MXL17 Full Round	
Current Meritor Number	Replacement Meritor Number
17XNM079C099H	Withdrawn - no replacement
17XNM081C117H	Withdrawn - no replacement
17XNM084C133H	Withdrawn - no replacement
17XNM085C140H	Withdrawn - no replacement
17XNM087C148H	Withdrawn - no replacement
17XNM088C143H	Withdrawn - no replacement
17XNM090C160H	No change
17XNM091C165H	No change
17XNM092C172H	17XNM125C172H
17XNM093C175H	17XNM125C172H
17XNM094C181H	17XNM126C181H
17XNM095C185H	17XNM126C181H
17XNM097C193H	17XNM127C193H
17XNM098C196H	17XNM127C193H

Table 2 – MXL17 Full Round Driveline

MXL17 Half Round (Easy Service™)	
Current Meritor Number	Replacement Meritor Number
17XTM079C099H	Withdrawn - no replacement
17XTM081C117H	Withdrawn - no replacement
17XTM084C133H	Withdrawn - no replacement
17XTM085C140H	Withdrawn - no replacement
17XTM087C148H	Withdrawn - no replacement
17XTM088C143H	Withdrawn - no replacement
17XTM092C172H	17XTM125C172H
17XTM093C175H	17XTM125C172H
17XTM094C181H	17XTM126C181H
17XTM095C185H	17XTM126C181H
17XTM097C193H	17XTM127C193H
17XTM098C196H	17XTM127C193H

Table 3 – MXL17 Half Round (Easy Service™) Driveline

If you have any questions relating to the above, please contact a Meritor Australia representative on +613-9300-5200.