

**Date:** August 2017

**Subject:** Service level axle housings to suit HN suspension for Kenworth Australia

**Models:** RT-40-140G, RT-40-145GP, RT-46-160GP and RT-50-160GP

**Dear Customer,**

This Product Information Letter provides Meritor® Australia’s part numbers for service level axle housings to suit Hendrickson’s HN suspensions for Kenworth Australia.

All service housings include welded suspension brackets, welded brackets for supporting the brake chamber bracket (camshaft tube), studs for installing the differential carrier and housing plugs.

In addition, some service housings may also include welded blocks on the housing spindle for ABS sensor installation. Refer to the table and notes below.

Axle model	Service housing wall thickness (mm)	Welded block for ABS	Service level housing part number
RD-20-140	12.7	No	C20 3121H1828S
RP-20-145		Yes	C21 3121H1828S
RR-20-140		No	C23 3121G1827S
RR-20-145		Yes	C22 3121G1827S
RP-23-160	16	No	C25 3121B1952S
RP-25-160		Yes	C26 3121B1952S
RR-23-160		No	C37 3121A1951S
RR-25-160		Yes	C36 3121A1951S

**Notes:**

1. For axles specified with ConMet 10 stud hubs, the service housings with welded ABS blocks are suitable.
2. For axles specified with spoke hubs, the service housings without welded ABS block should be ordered. For ABS installation, a bolt-on bracket (part number 2237-J-1440) and two long length cap screws (part number S-11018-1) are also required to be installed on the housing flange and brake spider interface.

For any questions relating to the above, please contact a Meritor® Australia representative on +613-9300-5200.

**Issued by Product Engineering  
Meritor HVSA Ltd**