PRODUCT INFORMATION LETTER #16-009



Meritor HVS Australia Ltd 70-76 Berkshire Road Sunshine North, Vic Australia

Date: December 2016

Subject: CTI Knuckle Options for MFS73 and FL941 - Update


Models: MFS73 AND FL941 Non Drive Front Steer Axle

Dear Customer

Meritor® would like to advise an update on the CTI systems that can be installed on the MFS73 AND FL941 steer axles.

Knuckles are available for MFS73 and FL941, to suit the **TIREBOSS™** system from Tire Pressure Control International Ltd (TPC), the **AIR CTI** system and the **Bigfoot** system.

The drilling and tapping of the knuckles for CTI systems is dependent on the particular system, and the appropriate knuckle is required to suit the axle model and brand of CTI being fitted.



PRODUCT INFORMATION LETTER #16-009



Meritor HVS Australia Ltd 70-76 Berkshire Road Sunshine North, Vic Australia

The following knuckle part numbers are available to suit each system;

		CTI System	
Axle Model		TPC and Bigfoot	AIR CTI
MFS73	Left hand knuckle	A-3111-S-19A	A-3111-U-4753
	Right hand knuckle	A-3111-T-20A	A-3111-V-4754
FL941	Left hand knuckle	A-3111-N-4642	A-3111-B-4786
	Right hand knuckle	A-3111-P-4644	A-3111-C-4787

The gross axle weight rating (GAWR) and service guidelines for both axle models are not affected by the use of these new knuckles. Refer to the specific manufacturer for the installation and service requirements of the CTI system.

If you have any questions relating to the above, please contact a Meritor® Australia representative on +613-9300-5200.

Issued by Product Engineering
Meritor HVSA Ltd