



Aftermarket Supersessions

COMPREHENSIVE LIST 2019 / 2021

| Month | Year | Old Part Number | Description | New Part Number |
|-----------|------|-----------------|--------------------------------------|-----------------|
| August | 2021 | E-612SBK | SLACK ADJUSTER MANUAL 5"/6"/7" 10SP | R824000 |
| August | 2021 | E-940SBK | SLACK ADJUSTER MANUAL 5.5"/6.5" 10SP | R824001 |
| August | 2021 | E-2458SBK | SLACK ADJUSTER MANUAL 5"/6"/7" 28SP | R824003 |
| August | 2021 | E-2459SBK | SLACK ADJUSTER MANUAL 5.5"/6.5" 28SP | R824004 |
| August | 2021 | E-1574SBK | SLACK ADJUSTER MANUAL Fruehauf | R824007 |
| February | 2021 | B983276X24 | CHAMBER ASSY TSE 2430 | G633276X24 |
| February | 2021 | B993276X24 | CHAMBER ASSY TSE 2430 | G643276X24 |
| February | 2021 | MCK1254 | KIT GUIDE PIN | MCK1255 |
| February | 2021 | 2214Q1343 | ADJUSTING RING | KIT2935 |
| January | 2021 | KIT2252L2CD2 | AIR DISC BRAKE - PAD KIT. ADB EX225L | KIT2252L2CG |
| December | 2020 | MLF8077 | AIR SPRING HENDRICKSON S-20010 | MAF9270 |
| December | 2020 | MLF8120 | AIR SPRING HOLLAND NEWAY 90557001 | MAF9039 |
| December | 2020 | MLF7112 | AIR SPRING HENDRICKSON S4771 | MAF8050 |
| November | 2020 | KIT4429 | DIFFERENTIAL - DCDL LOCK SWITCH | KIT4455 |
| November | 2020 | MLF8113 | AIR SPRING PETERBILT 03-02456 | MAF9069 |
| November | 2020 | MLF8114 | AIR SPRING HOLLAND NEWAY 90557006 | MAF9082 |
| September | 2020 | 25RY68-3KHP | YOKE ASSY | 25RHW002P |
| March | 2020 | E-9110 | SEAL GLADHAND | R950118 |
| March | 2020 | A23102G3465 | TIE ROD ASSY 1.66" DIA | R230593 |
| March | 2020 | M44D76617 | ROTOR ADB22X | M44D802082 |
| March | 2020 | M44D76618 | ROTOR ADB22X | M44D802081 |
| March | 2020 | 2257Z1014 | CLAMP | R005904A |
| November | 2019 | E-8017AU | NUT 1.25-12UNF 2A H=1.7" | 1227H554 |
| November | 2019 | E-8023AU | WASHER FLAT | 1229A1561 |
| November | 2019 | E-8127AU | U BOLT AC6S | 2297F9236 |
| November | 2019 | CB2108811X | BEARING CENTRE | CB3100121XSA |
| November | 2019 | A23102L4380 | TIE ROD ASSY 1.75" DIA | R230577 |
| November | 2019 | SC8191 | STUD 1/2x2.238x13-20 | R005798 |
| October | 2019 | E-3439 | BRAKE SHOE 15X4 UL | A3222F1072 |
| October | 2019 | E-3304 | BRAKE SHOE ASSY | A3222C1381 |
| October | 2019 | E-3823 | BRAKE SHOE | A3222J1440 |
| October | 2019 | E-3303 | BRAKE SHOE UNLINED | A3222E1383 |
| October | 2019 | KIT2252L2CD | KIT BRAKE PAD | KIT2252L2CD2 |
| October | 2019 | KIT225210 | EX225 PAD RETAINER KIT | KIT225281 |
| October | 2019 | 31965-33 | MTIS | H1965-33 |
| October | 2019 | E-FU16743N | AIR REGULATOR | R95516743N |
| August | 2019 | KIT225200 | KIT SLIDE PIN & BUSHING | KIT225280 |
| August | 2019 | A3102C4293 | TIE ROD ASSY 1.75" DIA | R230597 |
| June | 2019 | E-230323 | STRAP | LPHC393 |
| March | 2019 | 15X1892 | U BOLT M20x159x1.5 | 2297P9246 |



Aftermarket Supersessions

COMPREHENSIVE LIST 2017 / 2018

| Month | Year | Old Part Number | Description | New Part Number |
|----------|------|-----------------|-----------------------------------|-----------------|
| October | 2018 | E-9107-PL | COUPLING GLAD HAND BLUE PK75 | R950114-PL |
| October | 2018 | E-9108-PL | COUPLING GLAD HAND RED PK75 | R950115-PL |
| August | 2018 | E255 | KIT THRUST WASHER | E255-0 |
| August | 2018 | E-BC2424C | 2424 BRAKE SPRING UNIT | R872424C |
| August | 2018 | E-BC2430C | 2430 BRAKE SPRING UNIT | R872430C |
| August | 2018 | E-BC3030C | 3030 BRAKE SPRING UNIT | R873030C |
| August | 2018 | E-BC3636C | 3636 BRAKE SPRING UNIT | R873636C |
| July | 2018 | 1693565 | SPACER SLEEVE | E966.M |
| July | 2018 | A1205K2533 | SEAL ASY GREASE LX/MX500 | A1205X2650 |
| July | 2018 | MDP5103 | KIT BRAKE PAD | MDP5093 |
| July | 2018 | 15X1795 | BOLT .75x2.25x16 SPECIAL FL BRAKE | 15X1944 |
| June | 2018 | 60050298 | KIT CALIPER | KIT12010 |
| June | 2018 | E-SL140380 | VALVE PROTECTION | RSL140380 |
| June | 2018 | CP25RPLS | UNI JOINT PERMALUBE | CP25RPLS1 |
| March | 2018 | A13235W2779 | IAD ASSY RP2014X | A13235V3012 |
| March | 2018 | 21219322 | CAMSHAFT LH 350 610mm | S21219322 |
| March | 2018 | 21219342 | CAMSHAFT | S21219342 |
| March | 2018 | 21225020 | CAMSHAFT | S21225020 |
| March | 2018 | 21225021 | S21225021 | S21225021 |
| March | 2018 | 21227078 | CAMSHAFT RH 10S 610mm | S21227078 |
| March | 2018 | 21227079 | CAMSHAFT LH 10S 610mm | S21227079 |
| March | 2018 | 21227106 | CAMSHAFT | S21227106 |
| March | 2018 | 20RYSM40-24 | YOKE MALE, SPLINE | 20RYSM40-47 |
| March | 2018 | 63173 | SHOCK ABSORBER | M63173 |
| March | 2018 | 85703 | SHOCK ABSORBER | M85703 |
| March | 2018 | R806004 | SLACK ADJUSTER AUTO | R806004A |
| March | 2018 | 1245R1032 | CLEVIS M16X1.5 | 1245Q1083 |
| March | 2018 | 948599 | SHIM | 42X1568 |
| March | 2018 | 941291 | SHIM | 42X1567 |
| March | 2018 | 941292 | SHIM | 42X1569 |
| March | 2018 | 941293 | SHIM | 42X1570 |
| February | 2018 | 2237N14A | BRACKET ABS SENSOR | 2237J1440 |
| December | 2017 | 3100C8609 | CENTRE AXLE MFS66 KW | 3100C8739 |
| December | 2017 | MS2080451 | SCREW M8x45x1.3 GRD10.9 | MS2080452 |
| December | 2017 | 3237H1048 | RING ABS POLE | 9002166 |
| December | 2017 | S212221 | SCREW 3/4x2.75x10 GRD8/8.2 | S212222 |
| November | 2017 | 3100C8609 | CENTRE AXLE MFS66 KW | 3100C8739 |
| November | 2017 | MS2080451 | SCREW M8x45x1.3 GRD10.9 | MS2080452 |
| October | 2017 | E-6992A | SLACK ADJUSTER | E-6992B |



Aftermarket Supersessions

COMPREHENSIVE LIST 2017

| Month | Year | Old Part Number | Description | New Part Number |
|-----------|------|-----------------|---|-----------------|
| September | 2017 | R806002 | SLACK ADJUSTER AUTO CLEARANCE SENSING 1.5"X10 SPLINE | R806002A |
| September | 2017 | 21210215 | SPRING EXT/L BRAKE RETURN | 21210215PK10 |
| September | 2017 | A3235V3012 | IAD ASSY RD2014X | A3235H3310 |
| September | 2017 | A380021 | GEARSET SERVICE 3.90 | A380021390 |
| September | 2017 | A3297C1199 | SHAFT INPUT | A3297T1606 |
| September | 2017 | A4311T1060 | HUB & DRUM ASSY 20" R 6SP | A4311Z1066 |
| September | 2017 | 21212413 | BUTTON BUSH (KING PIN BRONZE) | 21212413B |
| August | 2017 | A33200U2153529 | CARRIER ASSY 17X BUS | A33200A2445529 |
| August | 2017 | A13235V3012 | IAD ASSY RP2014X | A13235H3310 |
| August | 2017 | 2297G33A | U BOLT AC6T 305mm | 2297D9234 |
| August | 2017 | 2297M65A | U BOLT AC6P 280mm | 2297G9237 |
| August | 2017 | 2297V48A | U BOLT AC6S 10.70" | 2297E9235 |
| August | 2017 | 2297W49A | U BOLT AC6S 11.9" | 2297F9236 |
| August | 2017 | A3280E551A | SPRING ASSY LEAF | A3176G1099 |
| August | 2017 | A3280R564A | SPRING ASSY LEAF AC6T | A3176H1100 |
| August | 2017 | A3280Z494A | SPRING ASSY LEAF AC6S | A3176F1098 |
| August | 2017 | E-11526 | MERITOR Q-PLUS STEER | E-11960 |
| July | 2017 | 2210J6614 | T CAM 1.25X24 SH | 2210W6731 |
| July | 2017 | 959238 | CAPSCREW INHEX, M10x2 | R006054 |
| July | 2017 | CKSK.1.1 | REPAIR KIT CALIPERS | CKSK.1.1.S |
| June | 2017 | 3133T326 | Tie Rod | 3133T7326K |
| June | 2017 | 3280L6720 | Hardware Misc Axle | M103280L6720 |
| June | 2017 | MS210045A1 | Hardware Misc Axle | MS210045A2 |
| June | 2017 | R806015 | Slack Adjuster | R806015A |
| June | 2017 | 3235V3012 | Diff Case | 3235H3310 |
| June | 2017 | BLKQ+R | Brake Lining Kit OE | BLKQPLUSR |
| April | 2017 | E-11527 | Meritor Camshaft Q-Plus Steer | E-11961 |
| April | 2017 | 16N3288X | Slip Yoke MXL | 16N3288XMXL |
| April | 2017 | 17N2749 | 1710 Flange Yoke Std | 17NF20 |
| April | 2017 | 17N45591 | Yoke 2.75" X 10 Spline 1710 | 17N46841X |
| April | 2017 | 17N46401 | 1710 Yoke Full Round | 17NYS32100 |
| April | 2017 | 18NYS32-12A | Yoke refer A 3260L 116 | 18N43381X |
| April | 2017 | 72NYS3645 | End Yoke | 72NYS3695 |
| April | 2017 | A13280R5452 | Yoke | 18N42551X |
| April | 2017 | A3280X6758 | Yoke 1710 2"X39 SPL | 17N46871X |
| April | 2017 | A3260G111 | Yoke | 16N46281X |
| April | 2017 | A3280F1982 | End Yoke | 17N44361X |
| April | 2017 | A3280T7118 | Yoke And Deflector Assy | 18N43571X |



Aftermarket Supersessions

COMPREHENSIVE LIST 2016 / 2017

| Month | Year | Old Part Number | Description | New Part Number |
|----------|------|-----------------|-----------------------------------|-----------------|
| April | 2017 | 17N32651X | Slip Yoke - MXL | 17N32651XMXL |
| April | 2017 | 17N32671X | Slip Yoke - MXL | 17N32671XMXL |
| April | 2017 | 17N46371 | 1710 Yoke T2111 | 17NYS3299 |
| April | 2017 | 17N46381X | 1710 Yoke T2111 | 17NYS3299A |
| April | 2017 | 17NYS32-56A3 | 1710 Yoke T2111 | 17NYS3299A3 |
| April | 2017 | 18N31371X | Slip Yoke MXL | 18N31371XMXL |
| April | 2017 | 18NYS38-8A2 | Yoke 2.38" X 46 Spline | 18N43581X |
| April | 2017 | 25RLS481A | Slip Yoke | 25RLS481A1S |
| April | 2017 | A23280D6764 | Flange Assy Companion | 5WCS32103A1 |
| April | 2017 | DEFR535 | Deflector Yoke RPL 20 | DEFR534 |
| March | 2017 | A13226T1112S | Cage,Thru Shaft & Sleeve Assy 145 | A13226T1112 |
| March | 2017 | E-11527 | Camshaft Meritor Q-Plus Steer | E-11961 |
| March | 2017 | 16N3288X | Slip Yoke MXL | 16N3288XMXL |
| March | 2017 | 17N2749 | 1710 Flange Yoke Std | 17NF20 |
| March | 2017 | 17N45591 | Yoke 2.75" X 10 Spline 1710 | 17N46841X |
| March | 2017 | 17N46401 | 1710 Yoke Full Round | 17NYS32100 |
| March | 2017 | 18NYS32-12A | Yoke Ref A 3260L 116 | 18N43381X |
| March | 2017 | 72NYS3645 | End Yoke | 72NYS3695 |
| March | 2017 | A13280R5452 | Yoke | 18N42551X |
| March | 2017 | A3280X6758 | Yoke 1710 2"X39 SPL | 17N46871X |
| March | 2017 | A3260G111 | Yoke | 16N46281X |
| March | 2017 | A3280F1982 | End Yoke | 17N44361X |
| March | 2017 | A3280T7118 | Yoke And Deflector Assy | 18N43571X |
| March | 2017 | 17N32651X | Slip Yoke - MXL | 17N32651XMXL |
| March | 2017 | 17N32671X | Slip Yoke - MXL | 17N32671XMXL |
| March | 2017 | 17N46371 | 1710 Yoke T2111 | 17NYS3299 |
| March | 2017 | 17N46381X | 1710 Yoke T2111 | 17NYS3299A |
| March | 2017 | 17NYS32-56A3 | 1710 Yoke T2111 | 17NYS3299A3 |
| March | 2017 | 18N31371X | Slip Yoke MXL | 18N31371XMXL |
| March | 2017 | 18NYS38-8A2 | Yoke 2.38" X 46 Spline | 18N43581X |
| March | 2017 | 25RLS481A | Slip Yoke | 25RLS481A1S |
| March | 2017 | A23280D6764 | Flange Assy Companion | 5WCS32103A1 |
| March | 2017 | DEFR535 | Deflector Yoke RPL 20 | DEFR534 |
| February | 2017 | MLF7115 | Air Spring | FS9101 |
| February | 2017 | E-11401 | Kit Auto Slack | E-11401A |
| February | 2017 | A13226T1112 | Cage,Thru Shaft & Sleeve Assy 145 | A13226T1112S |
| February | 2017 | E-11527 | Meritor Camshaft Q-Plus Steer | E-11961 |
| November | 2016 | A63200B2082411 | Carrier Assy RS1228B | A63200B2082463 |
| November | 2016 | A3256R1188 | Tool Bushing Instalation MTA | A3256F1228 |
| November | 2016 | 17NYS3838A | End Yoke | 17N47771X |



Aftermarket Supersessions

COMPREHENSIVE LIST 2015 / 2016

| Month | Year | Old Part Number | Description | New Part Number |
|-----------|------|-----------------|--|-----------------|
| November | 2016 | E-11401A | Kit Auto Slack | E-11401 |
| November | 2016 | 1229R2592 | Ring Snap | 1229N5422 |
| October | 2016 | MLF7115 | Air Spring suits Hendrickson/Neway | FS9101 |
| October | 2016 | A23200W2129 | Carrier Assy DT100 W/O | A23200S2411 |
| October | 2016 | E804M | Gearset RS1228B | E805.M |
| September | 2016 | 3299F7442 | Bracket Brake Chamber | 3299D7622 |
| September | 2016 | 3276Z1144 | Chamber Air Brake | 3276B1146 |
| August | 2016 | R407X | Uni Joint 1760 Full Rnd CP176N7P3 | M407X |
| July | 2016 | 18N31431XML | Slip Yoke | 18N31431X |
| July | 2016 | 53123627002 | Brake Drum, X30, 15.5X5" | 53123816002 |
| June | 2016 | A5333E135A | Hub and Drum Assemblies | A3333P4722 |
| June | 2016 | A6333E135A | Hub and Drum Assemblies | A4333P4722 |
| June | 2016 | A11333E135A | Hub and Drum Assemblies | A9333P4722 |
| June | 2016 | A12333E135A | Hub and Drum Assemblies | A10333P4722 |
| March | 2016 | MLF7177 | Air Spring | MLF8177 |
| March | 2016 | 3133N40AF | STRG Arm-Shot Peened ATD 24.49mm | 3133H9290F |
| February | 2016 | MLF7177 | Air Spring | MLF8177 |
| February | 2016 | 3107U1269 | Collar Fin | 3107S1397 |
| February | 2016 | 1228F1722 | Thrust Bearing Input | A1228S2255 |
| February | 2016 | MSK5002 | Pad Wear Warning Kit | MCK1358 |
| November | 2015 | MLF7000 | Air Spring Suits Volvo, Kassbohrer, Setra | MLF8000 |
| November | 2015 | MLF7001 | Air Spring Suits Evotrac, Mercedes, Volvo, York | MLF8001 |
| November | 2015 | MLF7003 | Air Spring Suits Mercedes | MLF8003 |
| November | 2015 | MLF7004 | Air Spring Suits Ansair, Dennis, Hino, MAN, York | MLF8004 |
| November | 2015 | MLF7007 | Air Spring Suits Dennis, DAF, Scania | MLF8007 |
| November | 2015 | MLF7008 | Air Spring Suits Leyland / DAF | MLF8008 |
| November | 2015 | MLF7009 | Air Spring Suits Dennis | MLF8009 |
| November | 2015 | MLF7010 | Air Spring Suits Dennis, Scania | MLF8010 |
| November | 2015 | MLF7011 | Air Spring Suits Volvo | MLF8011 |
| November | 2015 | MLF7012 | Air Spring Suits MAN | MLF8012 |
| November | 2015 | MLF7013 | Air Spring Suits MAN | MLF8013 |
| November | 2015 | MLF7026 | Air Spring Suits TMC | MLF8026 |
| November | 2015 | MLF7027 | Air Spring Suits TMC | MLF8027 |
| November | 2015 | MLF7028 | Air Spring Suits SAF | MLF8028 |
| November | 2015 | MLF7031 | Air Spring Suits SAF | MLF8031 |
| November | 2015 | MLF7034 | Air Spring Suits Scania | MLF8034 |
| November | 2015 | MLF7036 | Air Spring Suits SAF | MLF8036 |
| November | 2015 | MLF7042 | Air Spring Suits BPW | MLF8042 |
| November | 2015 | MLF7045 | Air Spring Suits BPW | MLF8045 |
| November | 2015 | MLF7046 | Air Spring Suits BPW | MLF8046 |



Aftermarket Supersessions

COMPREHENSIVE LIST 2015

| Month | Year | Old Part Number | Description | New Part Number |
|----------|------|-----------------|---|-----------------|
| November | 2015 | MLF7047 | Air Spring Suits BPW | MLF8047 |
| November | 2015 | MLF7066 | Air Spring Suits BPW | MLF8066 |
| November | 2015 | MLF7077 | Air Spring Suits Hendrickson | MLF8077 |
| November | 2015 | MLF7078 | Air Spring Suits Volvo | MLF8078 |
| November | 2015 | MLF7081 | Air Spring Suits Scania | MLF8081 |
| November | 2015 | MLF7082 | Air Spring Suits Ansair | MLF8082 |
| November | 2015 | MLF7084 | Air Spring Suits MAN | MLF8084 |
| November | 2015 | MLF7085 | Air Spring Suits MAN | MLF8085 |
| November | 2015 | MLF7086 | Air Spring Suits Volvo | MLF8086 |
| November | 2015 | MLF7087 | Air Spring Suits BPW | MLF8087 |
| November | 2015 | MLF7089 | Air Spring Suits BPW | MLF8089 |
| November | 2015 | MLF7090 | Air Spring Suits Mercedes | MLF8090 |
| November | 2015 | MLF7093 | Air Spring Suits BPW | MLF8093 |
| November | 2015 | MLF7104 | Air Spring Suits BPW | MLF8104 |
| November | 2015 | MLF7108 | Air Spring Suits Mercedes | MLF8108 |
| November | 2015 | MLF7109 | Air Spring Suits Mercedes | MLF8109 |
| November | 2015 | MLF7113 | Air Spring Suits Foden | MLF8113 |
| November | 2015 | MLF7114 | Air Spring Suits Hendrickson, Mack, Neway, W-Star, York | MLF8114 |
| November | 2015 | MLF7117 | Air Spring Suits Volvo | MLF8117 |
| November | 2015 | MLF7119 | Air Spring Suits Mercedes | MLF8119 |
| November | 2015 | MLF7120 | Air Spring Suits Hendrickson, Neway | MLF8120 |
| November | 2015 | MLF7125 | Air Spring Suits Iveco | MLF8125 |
| November | 2015 | MLF7135 | Air Spring Suits SAF | MLF8135 |
| November | 2015 | MLF7141 | Air Spring Suits Scania | MLF8141 |
| November | 2015 | MLF7142 | Air Spring Suits Scania | MLF8142 |
| November | 2015 | MLF7143 | Air Spring Suits Scania | MLF8143 |
| November | 2015 | MLF7144 | Air Spring Suits Scania | MLF8144 |
| November | 2015 | MLF7146 | Air Spring Suits Scania | MLF8146 |
| November | 2015 | MLF7148 | Air Spring Suits Renault | MLF8148 |
| November | 2015 | MLF7151 | Air Spring Suits Volvo | MLF8151 |
| November | 2015 | MLF7154 | Air Spring Suits Volvo | MLF8154 |
| November | 2015 | MLF7155 | Air Spring Suits Bova, Csepel, Ikarus (Cummins) | MLF8155 |
| November | 2015 | MLF7158 | Air Spring Suits MAN | MLF8158 |
| November | 2015 | MLF7170 | Air Spring Suits Volvo | MLF8170 |
| November | 2015 | MLF7177 | Air Spring Suits BPW | MLF8177 |
| November | 2015 | MLF7181 | Air Spring Suits Volvo | MLF8181 |
| November | 2015 | MLF7209 | Air Spring Suits Iveco | MLF8209 |
| October | 2015 | MSK5002 | Pad Wear Warning Kit | MCK1358 |
| October | 2015 | MLF7045 | Air Spring | MFL8045 |
| October | 2015 | MLF7114 | Air Spring | MFL8114 |
| October | 2015 | MLF7066 | Air Spring | MFL8066 |



Aftermarket Supersessions

COMPREHENSIVE LIST 2014 / 2015

| Month | Year | Old Part Number | Description | New Part Number |
|-----------|------|-----------------|--|-----------------|
| October | 2015 | 17N32401X | Slip Yoke MXL 1710 | 17N-3-2401X-MXL |
| October | 2015 | 3107U1269 | Collar Fin | 3107S1397 |
| October | 2015 | 1228F1722 | Thrust Bearing Input | A1228S2255 |
| September | 2015 | A3262A27A | Hub Cap 6 Hole 4P5 CR1612 | A3262X1506 |
| September | 2015 | A3262Z26A | Hub Cap 6 Hole 5P5 CR1613 | A3262Z1456 |
| September | 2015 | A3262B28A | Hub Cap 6 Hole 5P5 CR1644 | A3262Y1507 |
| August | 2015 | R806024 | Slack Adjuster Auto | R806024A |
| August | 2015 | R806023 | Slack Adjuster Auto | R806023A |
| August | 2015 | 09002134 | Ring - ABS (Exciter Ring) | 3237Y1195 |
| July | 2015 | R801079 | Kit Clevis, Auto Slack | R8083108 |
| July | 2015 | 2214W1271 | Adjusting Ring | 2214Q1343 |
| June | 2015 | A23102H34A | Torque Rod 535mm | A13102R44A |
| June | 2015 | A13102H8A | Torque Rod 560mm | A13102U47A |
| June | 2015 | A23102G7A | Torque Rod 535mm | A13102R44A |
| June | 2015 | 1069375 | Magnet | 2297W8733S |
| May | 2015 | 20RHM025B156H | Drive Shaft Inter Axle | 20RHM080B156H |
| April | 2015 | A23211G6065 | Brake Spider | A3211G6065 |
| March | 2015 | 17TYS3854A | 1710 Yoke F/R A3260G1229 | 17N471811X |
| March | 2015 | M85923 | Shock Absorber | M85931 |
| March | 2015 | E-04075 | Hub Cap | E-04975 |
| February | 2015 | E-6994A | Auto Slack Adjuster | E-6994B |
| February | 2015 | A11228B1666 | Bearing Inner Pinion | A1228G2217 |
| February | 2015 | MLF7186 | Air Spring | MLF8186 |
| February | 2015 | S18121 | Screw 1/2X1.5x20 Grd8/8.2 | S18122 |
| February | 2015 | 3235W2779 | Diff Case Plain | 3235V3012 |
| February | 2015 | CP25RPL | Uni Joint Permalube | CP25RPLS |
| February | 2015 | E-04075H | Cap-Hub, Freuhauf suits Hubo | E-04975H |
| February | 2015 | MLF7077 | Air Spring Hendrickson | MLF8077 |
| November | 2014 | 21204279 | Spring Assy Leaf | 21221244 |
| November | 2014 | 21222239FS | Air Spring | 21222239 |
| November | 2014 | A3297B1120 | Shaft Input RT153E | A3297B1120S |
| November | 2014 | E448 | Kit Gearset 4.10 Ratio FWD RT153E, replaces E448 | E448.M |
| November | 2014 | A1205L2794 | Seal Assy replaces 3192615 & 3192069 | A11205L2794 |
| November | 2014 | 21212440 | Anchor Pin replaces 21212440 | 21223366 |
| October | 2014 | S110321 | Bolt 5/8X4x18 GRD 8/8.2 | S1103222 |
| October | 2014 | A11228A1535 | Bearing Outer Pinion | A1228T2230.M |
| October | 2014 | E381 | Kit Diff Gear & Washer | E381.M |
| October | 2014 | B412841 | B412841F529 | B412841F529 |



Aftermarket Supersessions

COMPREHENSIVE LIST 2014

| Month | Year | Old Part Number | Description | New Part Number |
|-----------|------|-----------------|----------------------------------|-----------------|
| September | 2014 | A1225Q43A | Bushing | A1225Q1629 |
| September | 2014 | 20RHM016B182H | Drive Shaft Inner Axle | 20RHM085B180H |
| September | 2014 | A406741 | Gearset SHT 5.29 | A406741529 |
| September | 2014 | 20RY605 | Yoke Weld RPL | 20RY607 |
| August | 2014 | A1205V2492 | Seal Oil Hub | A1205Y2833 |
| August | 2014 | R005784G | Clamp Rim | R005784 |
| August | 2014 | 63173 | Shock Absorber | M63173 |
| July | 2014 | 21229392 | Hanger CS9 350 RH | 21231009 |
| July | 2014 | 21219322 | Camshaft LH 350 610mm | S21219322 |
| July | 2014 | 21219342 | Camshaft | S21219342 |
| July | 2014 | 21225020 | Camshaft | S21225020 |
| July | 2014 | 21227078 | Camshaft RH 10S 610mm | S21227078 |
| July | 2014 | 21227079 | Camshaft LH 10S 610mm | S21227079 |
| July | 2014 | 21227106 | Camshaft | S21227106 |
| June | 2014 | R005885G | Clamp Rim | R005885 |
| May | 2014 | 3226B1562 | Bearing Cage Assy | 3226P1628 |
| May | 2014 | RZ93.06.007 | Service Caliper L/H | LRG596 |
| May | 2014 | RZ93.06.008 | Service Caliper R/H | LRG597 |
| May | 2014 | 2210S5375 | Camshaft 10S 1.50" RH | R607077 |
| May | 2014 | A13222KC089 | Shoe & Lining Assy Brake Rr | A13222KC193 |
| May | 2014 | S2812B | Screw 1/2X1.25x13 Grd8 | S2810A2 |
| April | 2014 | 53123589002 | Brake Drum 16.5X5 X30 | 53123815002 |
| April | 2014 | 20RHM008B162H | Drive Shaft Inter Axle W H | 20RHM081B162H |
| April | 2014 | 23123572004 | Rotor, Disc Brake | 23123572009 |
| April | 2014 | 21225162 | Plate Wear Non Welded | 21224386 |
| April | 2014 | 17N32651X | Slip Yoke - MXL | 17N-3-2651X-MXL |
| April | 2014 | 17N32671X | Slip Yoke - MXL | 17N-3-2671X-MXL |
| April | 2014 | CMSK.3.7 | Kit Cover Plate Seal | SJ 4105 |
| March | 2014 | 2210U5637 | S Cam 10S 15.7" | R607089 |
| March | 2014 | 2210V5638S | S Cam 10S 15.7" | R607090 |
| March | 2014 | 21229391 | Frame Bracket LH Cs9 350 | 21231008 |
| March | 2014 | 2234C1069 | Gear-Diff Side, Fin | 2234H1438 |
| March | 2014 | 25WYS38-3A | RPL25 Yoke Spline | 25WYS38-13A |
| March | 2014 | 401754 | Shock Bushing | M401754 |
| March | 2014 | 401750000 | OES Accessory | M401750000 |
| March | 2014 | E-6993A | Slack Adjuster 1 1/2" 28Sp 5"-6" | E-6993B |
| February | 2014 | S1225S1189 | Bushing | 1225S1189 |
| February | 2014 | 21229391 | Frame Bracket LH CS9 350 | 21231008 |
| February | 2014 | A2237G1073 | Kit Sensor Abs Service | R955342 |